8.0 Photographs

Sample Site 1:
View north
December 2015

Sample Site 1:
View south
December 2015

Sample Site 1:
Substrate
December 2015

Sample Site 2:
View north
December 2015

Sample Site 2:
View south
December 2015

Sample Site 2:
Substrate
December 2015

Sample Site 4:
View south
Bowl Wetland
May 2014

Sample Site 4:
View north
December 2015

Sample Site 4:
View south
December 2015

Sample Site 5:
View east
December 2015

Sample Site 5:
View west
December 2015

Sample Site 5:
Substrate
December 2015

Sample Site 6:
View east
East West Drainage
December 2015

Sample Site 6:
View west
East West Drainage
December 2015

Sample Site 6:
Substrate
East West Drainage
December 2015

Sample Site 7:
View south
North South Drainage
December 2015

Sample Site 7:
View north
North South Drainage
December 2015

Sample Site 7:
Substrate
North South Drainage
December 2015



Sample Site 10:
View upstream
Tank Farm Creek
December 2015

Sample Site 10:
View downstream
Tank Farm Creek
December 2015

Sample Site 10:
Substrate
Tank Farm Creek
December 2015

Sample Site 11:
View upstream
Tank Farm Riparian
December 2015

Sample Site 11:
Substrate
Tank Farm Riparian
December 2015

Sample Site 13:
View west
Bowl Wetland
December 2015

Cross-Section B:
View upstream
December 2015

Cross-Section B:
View downstream
December 2015

Cross-Section B:
Substrate
December 2015

Cross-Section H:
View upstream
December 2015

Cross-Section H:
View downstream
December 2015

Cross-Section H:
Substrate
December 2015

Cross-Section I:
View upstream
December 2015

Cross-Section I:
View downstream
December 2015

Cross-Section I:
Substrate
December 2015

Cross-Section J:
View upstream
December 2015

Cross-Section J:
View downstream
December 2015

Cross-Section J:
Substrate
December 2015

This page intentionally blank.

Exhibit A – Delineation of Potentially Jurisdictional Wetlands and Waters

This page intentionally blank.

Exhibit A. Delineation of Potentially Jurisdictional Wetlands and Waters



0 0.1 0.2 0.4 0.6 0.8 1 Mile

Avila Ranch LLC
San Luis Obispo, CA

Map Updated: December 31, 2015 04:16 PM

ALTHOUSE AND MEADE, INC.
BIOLOGICAL AND ENVIRONMENTAL SERVICES

This page intentionally blank.

Exhibit B – Wetland Determination Data Forms

This page intentionally blank.

WETLAND DETERMINATION DATA FORM – Arid West Region

Project/Site: Avila Ranch City/County: San Luis Obispo Sampling Date: 4-11-14
Applicant/Owner: Steve Peck State: CA Sampling Point: 1 (14.1)
Investigator(s): J. Tillquist Section, Township, Range: Sec 10 T31S R12E
Landform (hillslope, terrace, etc.): depression Local relief (concave, convex, none): concave Slope (%): 1-2
Subregion (LRR): Mediterranean CA Lat: 35.23677 Long: -120.67432 Datum: WGS84
Soil Map Unit Name: Marimel sandy clay loam NWI classification: PEMAf
Are climatic / hydrologic conditions on the site typical for this time of year? Yes — No + (If no, explain in Remarks.)
Are Vegetation +, Soil +, or Hydrology — significantly disturbed? Are "Normal Circumstances" present? Yes — No +
Are Vegetation +, Soil —, or Hydrology + naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present? Yes + No —
Hydric Soil Present? Yes — No +
Wetland Hydrology Present? Yes + No —

Is the Sampled Area within a Wetland? Yes State No —

Remarks:
drought year

VEGETATION – Use scientific names of plants.

	Absolute % Cover	Dominant Species?	Indicator Status
Tree Stratum (Plot size:)			
1.			
2.			
3.			
4.			
	= Total Cover		
Sapling/Shrub Stratum (Plot size:)			
1.			
2.			
3.			
4.			
5.			
	= Total Cover		
Herb Stratum (Plot size: 1m²)			
1. Polypogon monspeliensis	15	Y	FACW
2. Helminthotheca echioides	5	N	FACU
3.			
4.			
5.			
6.			
7.			
8.			
	20 = Total Cover		
Woody Vine Stratum (Plot size:)			
1.			
2.			
	= Total Cover		

% Bare Ground in Herb Stratum 80 % Cover of Biotic Crust 0

Dominance Test worksheet:
Number of Dominant Species That Are OBL, FACW, or FAC: 1 (A)
Total Number of Dominant Species Across All Strata: 1 (B)
Percent of Dominant Species That Are OBL, FACW, or FAC: 100 (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply by:	
OBL species	0	x 1 =	0
FACW species	15	x 2 =	30
FAC species	0	x 3 =	0
FACU species	5	x 4 =	20
UPL species	0	x 5 =	0
Column Totals:	20 (A)		50 (B)

Prevalence Index = B/A = 2.5

Hydrophytic Vegetation Indicators:
+ Dominance Test is >50%
+ Prevalence Index is ≤3.0[1]
— Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)
+ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Hydrophytic Vegetation Present? Yes + No —

Remarks:
drought conditions and plowed ground - remnants of polypogon o evidence of inhibited crop growth

SOIL

Sampling Point: 1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth (inches)	Matrix Color (moist)	%	Redox Features Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
1-10	10YR2/1	100					SCL	
10-12+	10YR2/1	70	10YR5/2	30	D	M	SCL	no redox

[1]Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. [2]Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)

- — Histosol (A1)
- — Histic Epipedon (A2)
- — Black Histic (A3)
- — Hydrogen Sulfide (A4)
- — Stratified Layers (A5) **(LRR C)**
- — 1 cm Muck (A9) **(LRR D)**
- — Depleted Below Dark Surface (A11)
- — Thick Dark Surface (A12)
- — Sandy Mucky Mineral (S1)
- — Sandy Gleyed Matrix (S4)
- — Sandy Redox (S5)
- — Stripped Matrix (S6)
- — Loamy Mucky Mineral (F1)
- — Loamy Gleyed Matrix (F2)
- — Depleted Matrix (F3)
- — Redox Dark Surface (F6)
- — Depleted Dark Surface (F7)
- — Redox Depressions (F8)
- — Vernal Pools (F9)

Indicators for Problematic Hydric Soils[3]:

- — 1 cm Muck (A9) **(LRR C)**
- — 2 cm Muck (A10) **(LRR B)**
- — Reduced Vertic (F18)
- — Red Parent Material (TF2)
- — Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if present):

Type: none

Depth (inches): —

Hydric Soil Present? Yes ____ No +

Remarks:

soil mixing by recent farming activities, complicated evaluation of light soil features. However, no redox observed.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one required; check all that apply)

- — Surface Water (A1)
- — High Water Table (A2)
- — Saturation (A3)
- — Water Marks (B1) **(Nonriverine)**
- — Sediment Deposits (B2) **(Nonriverine)**
- — Drift Deposits (B3) **(Nonriverine)**
- — Surface Soil Cracks (B6)
- — Inundation Visible on Aerial Imagery (B7)
- — Water-Stained Leaves (B9)
- — Salt Crust (B11)
- — Biotic Crust (B12)
- — Aquatic Invertebrates (B13)
- — Hydrogen Sulfide Odor (C1)
- — Oxidized Rhizospheres along Living Roots (C3)
- — Presence of Reduced Iron (C4)
- — Recent Iron Reduction in Tilled Soils (C6)
- — Thin Muck Surface (C7)
- — Other (Explain in Remarks)

Secondary Indicators (2 or more required)

- — Water Marks (B1) **(Riverine)**
- — Sediment Deposits (B2) **(Riverine)**
- — Drift Deposits (B3) **(Riverine)**
- + Drainage Patterns (B10)
- — Dry-Season Water Table (C2)
- — Crayfish Burrows (C8)
- + Saturation Visible on Aerial Imagery (C9)
- — Shallow Aquitard (D3)
- + FAC-Neutral Test (D5)

Field Observations:

Surface Water Present? Yes ____ No ✓ Depth (inches): >12+

Water Table Present? Yes ____ No ✓ Depth (inches): >12+

Saturation Present? (includes capillary fringe) Yes ____ No ✓ Depth (inches): >12+

Wetland Hydrology Present? Yes + No ____

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

WETLAND DETERMINATION DATA FORM – Arid West Region

Project/Site: Avila Ranch City/County: San Luis Obispo Sampling Date: 4-11-14
Applicant/Owner: Steve Peck State: CA Sampling Point: 2 (0102)
Investigator(s): J. Tilligkeit Section, Township, Range: Sec 10 T31S R12E
Landform (hillslope, terrace, etc.): flat Local relief (concave, convex, none): none Slope (%): 0
Subregion (LRR): Mediterranean CA Lat: 35.23596 Long: -120.67547 Datum: WGS84
Soil Map Unit Name: Diablo/Cropley Clay NWI classification: PEMA+
Are climatic / hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ✓, Soil ____, or Hydrology ✓ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?** Yes State No ____
Hydric Soil Present?	Yes ____ No ✓	
Wetland Hydrology Present?	Yes ✓ No ____	

Remarks: drought year

VEGETATION – Use scientific names of plants.

	Absolute % Cover	Dominant Species?	Indicator Status
Tree Stratum (Plot size: n/a)			
1.			
2.			
3.			
4.			
	____ = Total Cover		
Sapling/Shrub Stratum (Plot size: n/a)			
1.			
2.			
3.			
4.			
5.			
	____ = Total Cover		
Herb Stratum (Plot size: 1m²)			
1. Convolvulus arvensis	1	N	UPL
2. Malvela leprosa	1	N	FACU
3. Helminthotheca echioides	1	N	FACU
4. Safflower crop	5	Y	UPL
5. Plantago ~~aquatica~~ lanceolata	Adjacent		FACU
6. Phalaris aquatica	Adjacent		FAC
7.			
8.			
	8 = Total Cover		
Woody Vine Stratum (Plot size: n/a)			
1.			
2.			
	____ = Total Cover		

% Bare Ground in Herb Stratum 90 % Cover of Biotic Crust 0

Dominance Test worksheet:
Number of Dominant Species That Are OBL, FACW, or FAC: 0 (A)
Total Number of Dominant Species Across All Strata: 1 (B)
Percent of Dominant Species That Are OBL, FACW, or FAC: 0 (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply by:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	2	x 4 =	8
UPL species	6	x 5 =	30
Column Totals:	8 (A)		38 (B)

Prevalence Index = B/A = 4.75

Hydrophytic Vegetation Indicators:
— Dominance Test is >50%
— Prevalence Index is ≤3.0[1]
— Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)
± Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks:
Minimal veg, mostly safflower crop. Evidence of inhibited crop growth. Roadside veg on higher ground & not hydrophytic.

SOIL

Sampling Point: 2

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth (inches)	Matrix Color (moist)	%	Redox Features Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0-13	10YR 2/1	100					SCl	
13-18	10YR 2/1	96	10YR 5/2	3	D	M	SCl	
			10YR 6/8	1	C	M		

[1]Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. [2]Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)

- ___ Histosol (A1)
- ___ Histic Epipedon (A2)
- ___ Black Histic (A3)
- ___ Hydrogen Sulfide (A4)
- ___ Stratified Layers (A5) **(LRR C)**
- ___ 1 cm Muck (A9) **(LRR D)**
- ___ Depleted Below Dark Surface (A11)
- ___ Thick Dark Surface (A12)
- ___ Sandy Mucky Mineral (S1)
- ___ Sandy Gleyed Matrix (S4)
- ___ Sandy Redox (S5)
- ___ Stripped Matrix (S6)
- ___ Loamy Mucky Mineral (F1)
- ___ Loamy Gleyed Matrix (F2)
- ___ Depleted Matrix (F3)
- ___ Redox Dark Surface (F6)
- ___ Depleted Dark Surface (F7)
- ___ Redox Depressions (F8)
- ___ Vernal Pools (F9)

Indicators for Problematic Hydric Soils[3]:

- ___ 1 cm Muck (A9) **(LRR C)**
- ___ 2 cm Muck (A10) **(LRR B)**
- ___ Reduced Vertic (F18)
- ___ Red Parent Material (TF2)
- ___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if present):

Type: n/a

Depth (inches): >18 inches

Hydric Soil Present? Yes ___ No ✓

Remarks:

too few depletions and concentrations and below 12 inches

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one required; check all that apply)

- ___ Surface Water (A1)
- ___ High Water Table (A2)
- ___ Saturation (A3)
- ___ Water Marks (B1) **(Nonriverine)**
- ___ Sediment Deposits (B2) **(Nonriverine)**
- ___ Drift Deposits (B3) **(Nonriverine)**
- ___ Surface Soil Cracks (B6)
- ___ Inundation Visible on Aerial Imagery (B7)
- ___ Water-Stained Leaves (B9)
- ___ Salt Crust (B11)
- ___ Biotic Crust (B12)
- ___ Aquatic Invertebrates (B13)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres along Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (2 or more required)

- ___ Water Marks (B1) **(Riverine)**
- ___ Sediment Deposits (B2) **(Riverine)**
- ___ Drift Deposits (B3) **(Riverine)**
- ___ Drainage Patterns (B10)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- ___ Saturation Visible on Aerial Imagery (C9)
- ___ Shallow Aquitard (D3)
- ___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present? Yes ___ No ✓ Depth (inches): >18"

Water Table Present? Yes ___ No ✓ Depth (inches): >18"

Saturation Present? (includes capillary fringe) Yes ___ No ✓ Depth (inches): >18"

Wetland Hydrology Present? Yes ✓ No ___

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

WETLAND DETERMINATION DATA FORM – Arid West Region

Project/Site: Avila Ranch City/County: San Luis Obispo Sampling Date: 4-11-14

Applicant/Owner: Steve Peck State: CA Sampling Point: 3 (pit 3)

Investigator(s): J. Tilligkert Section, Township, Range: Sec 10 T31S R12E

Landform (hillslope, terrace, etc.): Swale Local relief (concave, convex, none): Concave Slope (%): 1-2

Subregion (LRR): Mediterranean CA Lat: 35.273606 Long: -120.66929 Datum: WGS84

Soil Map Unit Name: Salinas silty clay loam NWI classification: PEMAf

Are climatic / hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)

Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓

Are Vegetation ✓, Soil ____, or Hydrology ✓ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ____	No ✓	**Is the Sampled Area within a Wetland?** Yes ____ No ✓
Hydric Soil Present?	Yes ____	No ✓	
Wetland Hydrology Present?	Yes ____	No ✓	

Remarks:
drought year, plowed field

VEGETATION – Use scientific names of plants.

	Absolute % Cover	Dominant Species?	Indicator Status
Tree Stratum (Plot size: N/A)			
1.			
2.			
3.			
4.			
	____ = Total Cover		
Sapling/Shrub Stratum (Plot size: N/A)			
1.			
2.			
3.			
4.			
5.			
	____ = Total Cover		
Herb Stratum (Plot size: m²)			
1. Metracaria discoidea	5	N	FACU
2. Spergula arvensis	5	N	UPL
3. Avena fatua	10	Y	UPL
4. Hordeum Volgare	25	Y	UPL
5.			
6.			
7.			
8.			
	45 = Total Cover		
Woody Vine Stratum (Plot size: N/A)			
1.			
2.			
	____ = Total Cover		

% Bare Ground in Herb Stratum 60 % Cover of Biotic Crust ____

Dominance Test worksheet:

Number of Dominant Species That Are OBL, FACW, or FAC: 0 (A)

Total Number of Dominant Species Across All Strata: 2 (B)

Percent of Dominant Species That Are OBL, FACW, or FAC: 0 (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply by:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	5	x 4 =	20
UPL species	40	x 5 =	200
Column Totals:	45 (A)		220 (B)

Prevalence Index = B/A = 4.89

Hydrophytic Vegetation Indicators:

— Dominance Test is >50%

— Prevalence Index is ≤3.0[1]

— Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)

≠ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Hydrophytic Vegetation Present? Yes ____ No ✓

Remarks:
plowed, consistent crop growth

SOIL

Sampling Point: 3

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth (inches)	Matrix Color (moist)	%	Redox Features Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0-13	10YR 2/1	70	7.5YR 5/8	1	C	M	SCl	minimal
	10YR 3/2	30						

[1]Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. [2]Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)

- ___ Histosol (A1)
- ___ Histic Epipedon (A2)
- ___ Black Histic (A3)
- ___ Hydrogen Sulfide (A4)
- ___ Stratified Layers (A5) **(LRR C)**
- ___ 1 cm Muck (A9) **(LRR D)**
- ___ Depleted Below Dark Surface (A11)
- ___ Thick Dark Surface (A12)
- ___ Sandy Mucky Mineral (S1)
- ___ Sandy Gleyed Matrix (S4)
- ___ Sandy Redox (S5)
- ___ Stripped Matrix (S6)
- ___ Loamy Mucky Mineral (F1)
- ___ Loamy Gleyed Matrix (F2)
- ___ Depleted Matrix (F3)
- ___ Redox Dark Surface (F6)
- ___ Depleted Dark Surface (F7)
- ___ Redox Depressions (F8)
- ___ Vernal Pools (F9)

Indicators for Problematic Hydric Soils[3]:

- ___ 1 cm Muck (A9) **(LRR C)**
- ___ 2 cm Muck (A10) **(LRR B)**
- ___ Reduced Vertic (F18)
- ___ Red Parent Material (TF2)
- ___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if present):

Type: N/A

Depth (inches): >13 inches

Hydric Soil Present? Yes ___ No ✓

Remarks:

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one required; check all that apply)

- ___ Surface Water (A1)
- ___ High Water Table (A2)
- ___ Saturation (A3)
- ___ Water Marks (B1) **(Nonriverine)**
- ___ Sediment Deposits (B2) **(Nonriverine)**
- ___ Drift Deposits (B3) **(Nonriverine)**
- ___ Surface Soil Cracks (B6)
- ___ Inundation Visible on Aerial Imagery (B7)
- ___ Water-Stained Leaves (B9)
- ___ Salt Crust (B11)
- ___ Biotic Crust (B12)
- ___ Aquatic Invertebrates (B13)
- ___ Hydrogen Sulfide Odor (C1)
- ___ Oxidized Rhizospheres along Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (2 or more required)

- ___ Water Marks (B1) **(Riverine)**
- ___ Sediment Deposits (B2) **(Riverine)**
- ___ Drift Deposits (B3) **(Riverine)**
- ___ Drainage Patterns (B10)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- ___ Saturation Visible on Aerial Imagery (C9)
- ___ Shallow Aquitard (D3)
- ___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present? Yes ___ No ✓ Depth (inches): >13in

Water Table Present? Yes ___ No ✓ Depth (inches): >13in

Saturation Present? (includes capillary fringe) Yes ___ No ✓ Depth (inches): >13in

Wetland Hydrology Present? Yes ___ No ✓

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

WETLAND DETERMINATION DATA FORM – Arid West Region

Project/Site: Avila Ranch City/County: San Luis Obispo Sampling Date: 5-8-14
Applicant/Owner: Steve Peck State: CA Sampling Point: 4 (of 4)
Investigator(s): J. Tilligkeit + LD Althouse Section, Township, Range: Sec 11 T31S R12E
Landform (hillslope, terrace, etc.): Swale/bowl Local relief (concave, convex, none): Concave Slope (%): 0-5
Subregion (LRR): Mediterranean CA Lat: 35.23723 Long: -120.66508 Datum: WGS84
Soil Map Unit Name: NWI classification:
Are climatic / hydrologic conditions on the site typical for this time of year? Yes ____ No ✓ (If no, explain in Remarks.)
Are Vegetation ✓, Soil ✓, or Hydrology ____ significantly disturbed? Are "Normal Circumstances" present? Yes ____ No ✓
Are Vegetation ✓, Soil ____, or Hydrology ✓ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present?	Yes ✓ No ____	**Is the Sampled Area within a Wetland?** Yes State No ____
Hydric Soil Present?	Yes ____ No ✓	
Wetland Hydrology Present?	Yes ✓ No ____	

Remarks:
plowed field, drought year

VEGETATION – Use scientific names of plants.

	Absolute % Cover	Dominant Species?	Indicator Status
Tree Stratum (Plot size: N/A)			
1.			
2.			
3.			
4.			
	= Total Cover		
Sapling/Shrub Stratum (Plot size: N/A)			
1.			
2.			
3.			
4.			
5.			
	= Total Cover		
Herb Stratum (Plot size: m²)			
1. Malvella leprosa	5	Y	FACU
2. Convolvulus arvensis	2	N	N/A
3. Avena sativa	1	N	UPL
4.			
5.			
6.			
7.			
8.			
	8 = Total Cover		
Woody Vine Stratum (Plot size: N/A)			
1.			
2.			
	= Total Cover		

% Bare Ground in Herb Stratum 92 % Cover of Biotic Crust 0

Dominance Test worksheet:
Number of Dominant Species That Are OBL, FACW, or FAC: 0 (A)
Total Number of Dominant Species Across All Strata: 1 (B)
Percent of Dominant Species That Are OBL, FACW, or FAC: 0 (A/B)

Prevalence Index worksheet:

Total % Cover of:		Multiply by:	
OBL species	0	x 1 =	0
FACW species	0	x 2 =	0
FAC species	0	x 3 =	0
FACU species	5	x 4 =	20
UPL species	1	x 5 =	5
Column Totals:	6 (A)		25 (B)

Prevalence Index = B/A = 4.2

Hydrophytic Vegetation Indicators:
— Dominance Test is >50%
— Prevalence Index is ≤3.0[1]
— Morphological Adaptations[1] (Provide supporting data in Remarks or on a separate sheet)
+ Problematic Hydrophytic Vegetation[1] (Explain)

[1]Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Hydrophytic Vegetation Present? Yes ✓ No ____

Remarks:
Pattern of veg suggests ~~leaf~~ long periods of saturation that inhibited crop growth. Outside upland from bowl feature are more dense, ~10% cover. All plants < 6" tall

SOIL

Sampling Point: 4

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth (inches)	Matrix Color (moist)	%	Redox Features Color (moist)	%	Type[1]	Loc[2]	Texture	Remarks
0-5	10YR 3/1	100	—	—	—	—	C	
5-17	10YR 3/1	100	—	—	—	—	C	
18+	10YR 3/1	95	10YR 6/8	1	C	M	C	oxidized rhizos
			10YR 4/6	5	C	M		10YR 6/8

[1]Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. [2]Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)

- ___ Histosol (A1)
- ___ Histic Epipedon (A2)
- ___ Black Histic (A3)
- ___ Hydrogen Sulfide (A4)
- ___ Stratified Layers (A5) **(LRR C)**
- ___ 1 cm Muck (A9) **(LRR D)**
- ___ Depleted Below Dark Surface (A11)
- ___ Thick Dark Surface (A12)
- ___ Sandy Mucky Mineral (S1)
- ___ Sandy Gleyed Matrix (S4)
- ___ Sandy Redox (S5)
- ___ Stripped Matrix (S6)
- ___ Loamy Mucky Mineral (F1)
- ___ Loamy Gleyed Matrix (F2)
- ___ Depleted Matrix (F3)
- ___ Redox Dark Surface (F6)
- ___ Depleted Dark Surface (F7)
- ___ Redox Depressions (F8)
- ___ Vernal Pools (F9)

Indicators for Problematic Hydric Soils[3]:

- ___ 1 cm Muck (A9) **(LRR C)**
- ___ 2 cm Muck (A10) **(LRR B)**
- ___ Reduced Vertic (F18)
- ___ Red Parent Material (TF2)
- ___ Other (Explain in Remarks)

[3]Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.

Restrictive Layer (if present):

Type: none

Depth (inches): >18in

Hydric Soil Present? Yes ___ No ✓

Remarks:

Area plowed but still much darker than upland areas.
Redox features present at 18 inches.

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one required; check all that apply)

- ___ Surface Water (A1)
- ___ High Water Table (A2)
- ___ Saturation (A3)
- ___ Water Marks (B1) **(Nonriverine)**
- ___ Sediment Deposits (B2) **(Nonriverine)**
- ___ Drift Deposits (B3) **(Nonriverine)**
- ___ Surface Soil Cracks (B6)
- ___ Inundation Visible on Aerial Imagery (B7)
- ___ Water-Stained Leaves (B9)
- ___ Salt Crust (B11)
- ___ Biotic Crust (B12)
- ___ Aquatic Invertebrates (B13)
- ___ Hydrogen Sulfide Odor (C1)
- + Oxidized Rhizospheres along Living Roots (C3)
- ___ Presence of Reduced Iron (C4)
- ___ Recent Iron Reduction in Tilled Soils (C6)
- ___ Thin Muck Surface (C7)
- ___ Other (Explain in Remarks)

Secondary Indicators (2 or more required)

- ___ Water Marks (B1) **(Riverine)**
- ___ Sediment Deposits (B2) **(Riverine)**
- ___ Drift Deposits (B3) **(Riverine)**
- ___ Drainage Patterns (B10)
- ___ Dry-Season Water Table (C2)
- ___ Crayfish Burrows (C8)
- + Saturation Visible on Aerial Imagery (C9)
- ___ Shallow Aquitard (D3)
- ___ FAC-Neutral Test (D5)

Field Observations:

Surface Water Present? Yes ___ No ✓ Depth (inches): >18in

Water Table Present? Yes ___ No ✓ Depth (inches): >18in

Saturation Present? (includes capillary fringe) Yes ___ No ✓ Depth (inches): >18in

Wetland Hydrology Present? Yes ✓ No ___

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

Soil moist but not saturated below 6 inches. Moisture appears to concentrate in this topography bowl feature.